



VEHICLE INSPECTION REPORT

HW14LPE

Vauxhall Adam 1.2i Jam 3dr

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	20/06/2014	Body Style	Hatchback	Last service miles	72,347
Year	2014	Keys	1	MOT Due	29/09/2026
Mileage	80,116 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Printout	Gears	5
Colour	WHITE	Number of stamps	5	Doors	3
VIN	W0L0MAP08E6077493	Last service date	19/09/2025		

last service 19/9/25 @ 72,347 miles (5 main dealer) Low clutch
 Clutch pedal sticking
 Exhaust blowing
 Intermittent window fault

Tyres

NSF	NEXEN	5.0mm
NSR	NEXEN	5.0mm
OSF	NEXEN	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Cruise control
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Passenger airbag
- Partial leather seat trim
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Wheel nsf
Scratched
Over 50mm



4: Door nsf
Scratched
UpTo 25mm Thru Paint



5: Qtr Panel nsr
Dented
With Paint Damage



6: Wheel nsr
Scratched
Over 50mm



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Qtr Panel osr
Dented
With Paint Damage



9: Door osf
Chipped
Edge Chip



10: Bumper Front
Insecure
Action Required



11: Wing osf
Chipped
1 To 5



12: Wheel osf
Scratched
Over 50mm



13: Screen Front
Chipped
UpTo 10mm



14: Roof
Chipped
Edge Chip

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK