



VEHICLE INSPECTION REPORT

LM18NVF

Audi A1 1.4 TFSI Sport Nav 5dr S Tronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Buyer To Apply



Details

Reg. date	30/05/2018	Body Style	Hatchback	Last service miles	11,381
Year	2018	Keys	1	MOT Due	01/06/2027
Mileage	27,394 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	PETROL	Service documents	Printout	Gears	7
Colour	BLACK	Number of stamps	1	Doors	5
VIN	WAUZZZ8X8JB068746	Last service date	16/06/2021		

£90 ADDITIONAL FEE

NO V5

Last service 16/06/2021 at 11,381 miles- 1 service

Tyres


NSF	BRIDGESTONE	4.0mm
NSR	GOODYEAR	Damaged
OSF	BRIDGESTONE	4.0mm
OSR	GOODYEAR	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Navigation system
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- PAS
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Tyre nsr
Damaged
Replace



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bonnet
Scratched
Over 25mm Thru Paint



4: Wheel nsf
Dented
UpTo 30mm (Alloy)



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Door nsf
Chipped
1 To 5



7: Door nsr
Scratched
UpTo 25mm Thru Paint



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



11: Wheel osr
Scratched
Up To 50mm



12: Door osr
Dented
Between 10mm + 30mm



13: Door osf
Chipped
Edge Chip



14: Wing osf
Scratched
UpTo 25mm Thru Paint



15: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK