



VEHICLE INSPECTION REPORT

VA16XFY

Nissan X-Trail 1.6 dCi Tekna 5dr 4WD [7 Seat]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
5

Details

Reg. date	15/07/2016	Body Style	Estate	Last service miles	98,984
Year	2016	Keys	2	MOT Due	27/08/2026
Mileage	106,791 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	9	Doors	5
VIN	JN1JCNT32U0011503	Last service date	07/08/2025		

Last Service - 07.08.2025 at 98984 miles (9 services) Driver side window faulty

Tyres



NSF	FALKEN	Damaged
NSR	FALKEN	5.0mm
OSF	FALKEN	5.0mm
OSR	FALKEN	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Space saver spare wheel
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- PAS
- Digital radio
- Opening panoramic glass roof
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Cracked
UpTo 25mm



3: Bumper Front Moulding
Broken
Replace



4: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



5: Wing nsf
Chipped
1 To 5



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Door nsr
Dented
Between 10mm + 30mm



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: Tailgate
Scratched
UpTo 25mm Thru Paint



12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Wheel osr
Scratched
Over 50mm



14: Door osr
Dented
Between 10mm + 30mm



15: Door osr
Scratched
Over 25mm Thru Paint



16: Door osf
Dented
2 Or Less UpTo 10mm




17: Door osf
Scratched
UpTo 25mm Thru Paint



18: Wing osf
Scratched
Over 25mm Thru Paint



19: Wheel osf
Scratched
Over 50mm



20: Roof
Chipped
Multiple Chips



21: Tyre nsf
 Damaged
 Replace



22: Sill os
 Scratched
 Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	Fault	Steering	OK
Sat nav	OK		