



# VEHICLE INSPECTION REPORT

**RE14OHL**

## Audi A1 1.2 TFSI Sport 3dr

nama  
 GRADE  
**4**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	09/06/2014	Body Style	Hatchback	Last service miles	37,720
Year	2014	Keys	1	MOT Due	10/01/2027
Mileage	128,301 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Printout	Gears	5
Colour	WHITE	Number of stamps	1	Doors	3
VIN	WAUZZZ8X3EB113758	Last service date	12/12/2016		

£90 ADDITIONAL FEE

LAST SERVICE 12/12/2016 @ 37,720 MILES (1 SERVICE, MAIN DEALER) Service due message displayed

Airbag light is on

Epc warning light is on

Eml light is on

Car been plugged in and detected

Throttle pedal position sensor B circuit low input

### Tyres

NSF	FARROAD	4.0mm
NSR	BUDGET	Illegal
OSF	FARROAD	3.0mm
OSR	BUDGET	5.0mm


### Spare

## Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- PAS
- Digital radio
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Rear wiper
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Central locking
- Service indicator
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Scratched  
Over 50mm



2: Door osf  
Chipped  
1 To 5



3: Qtr Panel osr  
Dented  
With Paint Damage



4: Wheel nsr  
Scratched  
Over 50mm



5: Bumper Rear  
Scratched  
Over 100mm Thru Paint



6: Qtr Panel nsr  
Dented  
With Paint Damage



7: Wheel nsr  
Scratched  
Over 50mm



8: Wheel nsf  
Scratched  
Over 50mm



9: Bumper Front  
Cracked  
UpTo 25mm



10: Bumper Front  
Poor Previous Repair  
Paint Flake



11: Bonnet  
Chipped  
1 To 5

### Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	Fault	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK