



# VEHICLE INSPECTION REPORT

**GX70VCU**

## Honda Civic 1.0 VTEC Turbo 126 SR 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	29/01/2021	Body Style	Hatchback	Last service miles	43,157
Year	2021	Keys	2	MOT Due	28/01/2027
Mileage	46,783 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	5	Doors	5
VIN	SHHFK6760LU003105	Last service date	19/01/2026		

Last service 19/01/2026 at 43,157 miles- 5 main dealer services

### Tyres


NSF	RAPID	5.0mm
NSR	SUNNY	4.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm

Spare

## Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Radio/CD
- Climate control
- Metallic Paint
- Traction control
- Cloth seat trim
- Park assist camera
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Door osf  
Chipped  
1 To 5



2: Door osf  
Chipped  
Edge Chip



3: Door osr  
Chipped  
1 To 5



4: Wheel osf  
Scratched  
Over 50mm



5: Wheel osr  
Scratched  
Over 50mm



6: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



7: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



8: Bumper Rear  
Chipped  
1 To 5



9: Qtr Panel nsr  
Dented  
With Paint Damage



10: Door nsr  
Dented  
With Paint Damage



11: Wheel nsr  
Scratched  
Over 50mm



12: Door nsf  
Dented  
With Paint Damage



13: Wheel nsf  
Scratched  
Over 50mm



14: Bumper Front  
Dented  
With Paint Damage



15: Sill Panel Trim ns  
Scratched (Painted)  
Over 25mm Thru Paint

16: Other  
N/A  
N/A

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK