

# VEHICLE INSPECTION REPORT

**GK13XKZ**

## Hyundai I10 1.2 Style 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	26/03/2013	Body Style	Hatchback	Last service miles	69,886
Year	2013	Keys	2	MOT Due	28/10/2026
Mileage	76,487 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	SILVER	Number of stamps	10	Doors	5
VIN	MALAN51CLDM345998	Last service date	27/10/2025		

Last service 27/10/2025 at 69,886 miles- 10 services (6 main dealer) Clutch slipping

### Tyres

NSF	NEXEN	4.0mm
NSR	NEXEN	4.0mm
OSF	NEXEN	3.0mm
OSR	HANKOOK	4.0mm
Spare		

## Features


- Heated front seat
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Air conditioning
- Metallic Paint
- Traction control
- Alloy wheels
- Radio/CD
- Front electric windows
- ABS
- Central locking
- Body coloured bumpers
- Rear electric windows
- Drivers airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Scratched  
Over 50mm



2: Door osr  
Rusted  
Over 5mm



3: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



4: Wheel osr  
Scratched  
Over 50mm



5: Bumper Rear  
Scratched  
Up To 25mm Thru Paint



6: Wheel nsr  
Scratched  
Over 50mm



7: Door nsr  
Rusted  
Over 5mm



8: Other  
N/A  
N/A




9: Wheel nsf  
Scratched  
Over 50mm




10: Bumper Front  
Poor Previous Repair  
Paint Flake



11: Bonnet  
Chipped  
1 To 5



12: Roof  
Rusted  
UpTo 5mm



13: Roof  
Dented  
Between 10mm + 30mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	Fault
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK