



VEHICLE INSPECTION REPORT

YG20DJV

BMW 3 Series 320d Sport 5dr Step Auto

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	03/03/2020	Body Style	Estate	Last service miles	80,671
Year	2020	Keys	2	MOT Due	13/08/2026
Mileage	87,442 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	DIESEL	Service documents	Printout	Gears	8
Colour	WHITE	Number of stamps	5	Doors	5
VIN	WBA6L52090FJ53286	Last service date	27/02/2026		

£100 ADDITIONAL FEE

last service 27/2/26 @ 80,671 miles 5 service 4 main dealer) Service overdue

Tyres



NSF	BUDGET	2.0mm
NSR	FALKEN	2.0mm
OSF	BUDGET	3.0mm
OSR	FALKEN	2.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Solid Paint
- Traction control
- Leather seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Door osf
Chipped
1 To 5



2: Door osf
Chipped
Edge Chip



3: Door osr
Chipped
1 To 5



4: Other
N/A
N/A



5: Bumper Rear
Chipped
1 To 5



6: Tailgate
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Dented
Between 10mm + 30mm



8: Door nsf
Dented
2 Or Less UpTo 10mm



9: Door nsf
Chipped
1 To 5



10: Bumper Front
Scratched
25 to 100mm Thru Paint



11: Bonnet
Chipped
1 To 5



12: Screen Front
Chipped
Over 10mm



13: Roof
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK