



VEHICLE INSPECTION REPORT

GU67WTV

Vauxhall Corsa 1.4 Diamond 5dr

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	28/09/2017	Body Style	Hatchback	Last service miles	94,023
Year	2017	Keys	2	MOT Due	18/10/2026
Mileage	104,077 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	WHITE	Number of stamps	8	Doors	5
VIN	W0L0XEP68H4291382	Last service date	14/10/2025		

Last Service -14.10.2025 at 94023 miles (8 services)

Tyres

NSF	PACE	5.0mm
NSR	RAPID	5.0mm
OSF	PACE	5.0mm
OSR	RAPID	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Remote central locking
- Heated front seat
- Telephone
- Air conditioning
- Solid Paint
- Traction control
- Cloth seat trim
- Park assist camera
- Radio/CD
- Climate control
- ABS
- Tyre pressure monitor
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wheel osr
Scratched
Over 50mm



3: Wheel nsr
Corroded
Light



4: Wheel nsf
Corroded
Light



5: Seat Base Cover osf
Torn
Over 3mm



6: Door osf
Chipped
1 To 5



7: Door osr
Dented
With Paint Damage



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Qtr Panel nsr
Chipped
1 To 5



10: Door nsr
Chipped
1 To 5



11: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



12: Bumper Front
Chipped
Multiple Chips



13: Bonnet
Chipped
Multiple Chips



14: A Post os
Chipped
1 To 5



15: Roof
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK