



# VEHICLE INSPECTION REPORT

**LV16DUA**

## RENAULT CAPTUR 1.5 dCi 110 Signature Nav 5dr

Inspection	Vehicle
	VAT Margin
	V5 Present

### Details

<b>Reg. date</b>	30/03/2016	<b>Body Style</b>	Hatchback	<b>MOT Due</b>	Expired
<b>Year</b>	2016	<b>Service history</b>	Yes	<b>Gearbox</b>	MANUAL
<b>Mileage</b>	54,882 Miles Warranted	<b>Service documents</b>	Service Book	<b>Gears</b>	6
<b>Fuel Type</b>	DIESEL	<b>Number of stamps</b>	7	<b>Doors</b>	5
<b>Colour</b>	RED/BLACK	<b>Last service date</b>	26/06/2025		
<b>VIN</b>	VF12RBR1C55382069	<b>Last service miles</b>	40,125		

£100 ADDITIONAL FEE  
 Last Service - 26.06.2025 at 51977 miles (7 services)  
 Cambelt Replaced 18.07.2022 @ 40125 miles

### Tyres

NSF
NSR
OSF
OSR
Spare