



VEHICLE INSPECTION REPORT

EF22DYB

Mercedes-Benz C Class C300d AMG Line 5dr 9G-Tronic

nama
GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	13/08/2022	Body Style	Estate	Last service miles	62,870
Year	2022	Keys	2	MOT Due	13/08/2026
Mileage	78,401 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	ELECTRIC DIESEL	Service documents	Printout	Gears	9
Colour	BLACK	Number of stamps	5	Doors	5
VIN	W1K2062062F055232	Last service date	18/12/2025		

£90 ADDITIONAL FEE

LAST SERVICE 18/12/2025 @ 62,870 MILES (5 SERVICES, ALL MAIN DEALER) Top up ad blue message display

Tyres


NSF	HANKOOK	6.0mm
NSR	BRIDGESTONE	4.0mm
OSF	HANKOOK	6.0mm
OSR	BRIDGESTONE	4.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Leather seat trim
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Traction control
- Alloy wheels
- Front parking sensor
- PAS
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking

Photos





Condition Check




Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: A Post ns
Chipped
1 To 5



6: Door nsf
Chipped
Edge Chip



7: Door nsr
Chipped
Edge Chip




8: Wheel nsr
Scratched
Over 50mm



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Wheel osr
Scratched
Over 50mm



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint



12: Door osr
Dented
2 Or Less Up To 10mm



13: Door osr
Chipped
1 To 5



14: Door osf
Chipped
Edge Chip



15: A Post os
Dented
With Paint Damage



16: Wheel osf
Scratched
Over 50mm



17: Wing osf
Chipped
1 To 5



18: Roof
Chipped
Edge Chip

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK