



VEHICLE INSPECTION REPORT

LB13DFZ

Land Rover Range Rover 5.0L Super Charge V8 Left Hand Drive

**Imported
Inspection**

Serious Damage?	No	Vehicle	
		VAT	Margin
		V5	Buyer To Apply

nama
GRADE
2

Details

Reg. date	01/10/2013	Body Style	Hatchback	CAP Clean	£18,250.00
Year	2013	Keys	1	CAP Average	£16,900.00
Mileage	38,264 Miles Not Warranted	Number of stamps	5	Gearbox	Automatic
Fuel Type	Petrol	Last service date	18/03/2022	Doors	5
Colour	BLACK	Last service miles	34,137		
VIN	SALGV2EF0EA127866	MOT Due	Expired		

Being sold on behalf of the High Court . Left Hand Drive .Copy of old V5 only. Registration number to be advised.. Chauffer pack and believed to have bullet proof glass . Date error on Landover on line service history .Email from servicing dealership confirming correct service mileages . Cap figures based on right hand drive vehicle.

Tyres

NSF	CONTINENTAL	2.0mm
NSR	CONTINENTAL	4.0mm
OSF	CONTINENTAL	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Telephone
- Electric sunroof
- Electrically adjustable passenger seat
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Front armrest
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Front electric windows
- Metallic Paint
- Traction control
- Leather seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Rear armrest
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Chipped
1 To 5



3: Door osf
Chipped
Edge Chip



4: Wheel osr
Scratched
Over 50mm



5: Tailgate
Scratched
Over 25mm Thru Paint



6: Wheel nsr
Scratched
Over 50mm



7: Door nsf
Chipped
Edge Chip



8: Bumper Front
Scratched
25 to 100mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		