



VEHICLE INSPECTION REPORT

GV22SZJ

Volkswagen Golf 1.5 TSI 150 Style 5dr

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	26/08/2022	Body Style	Hatchback	Last service miles	20,158
Year	2022	Keys	2	MOT Due	25/08/2026
Mileage	25,861 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	BLUE	Number of stamps	2	Doors	5
VIN	WVWZZZCD3PW002235	Last service date	19/06/2025		

£90 ADDITIONAL FEE

Last Service - 19.06.2025 at 20158 miles (2 main dealer services)

Tyres

NSF	NEXEN	3.0mm
NSR	NEXEN	5.0mm
OSF	NEXEN	3.0mm
OSR	NEXEN	5.0mm

Spare

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Door osf
Chipped
1 To 5



2: Qtr Panel nsr
Poor Previous Repair
Poor Paint



3: Door nsf
Chipped
1 To 5



4: Bumper Front
Scratched
UpTo 25mm Thru Paint



5: Door nsr
Poor Previous Repair
Poor Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK