



VEHICLE INSPECTION REPORT

YE18XLZ

BMW 5 Series 520d M Sport 4dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	21/05/2018	Body Style	Saloon	Last service miles	87,025
Year	2018	Keys	1	MOT Due	18/09/2026
Mileage	102,248 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	8
Colour	WHITE	Number of stamps	4	Doors	4
VIN	WBAJC32060WE58469	Last service date	22/05/2025		

£90 ADDITIONAL FEE.

Last service 22/05/2025 at 87,025 miles- 4 services. Print Key fob missing buttons
Eml light on

Tyres

NSF	LANDSAIL	3.0mm
NSR	PIRELLI	2.0mm
OSF	LANDSAIL	4.0mm
OSR	GOODRIDE	Illegal
Spare		

Features


- Bluetooth connection
- Navigation system
- Service indicator
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Remote central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Side airbags
- Leather seat trim
- Front parking sensor
- PAS
- Digital radio
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



4: Wheel osr
Scratched
Over 50mm



5: Bumper Rear
Poor Previous Repair
Paint Flake



6: Qtr Panel nsr
Dented
With Paint Damage



7: Wheel nsr
Scratched
Over 50mm



8: Door nsr
Chipped
Edge Chip



9: Sill Panel Trim ns
Scratched (Painted)
Over 25mm Thru Paint



10: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Not Thru Paint



11: Wheel nsf
Scratched
Over 50mm



12: Bumper Front
Scratched
Over 100mm Thru Paint



13: Bonnet
Scratched
UpTo 25mm Not Thru Paint



14: Bumper Rear Moulding
Scratched (Painted)
Over 25mm Thru Paint



15: Door Pad osr
Scuffed
Over 25mm



16: Door Pad nsr
Scuffed
Over 25mm



17: Fascia Trim
Missing
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK