



VEHICLE INSPECTION REPORT

HN17CVA

RENAULT CAPTUR 0.9 TCE 90 Dynamique Nav 5dr

Inspection	Vehicle
	VAT Margin
	V5 Present

Details

Reg. date	05/05/2017	Body Style	Hatchback	MOT Due	16/11/2026
Year	2017	Service history	Yes	Gearbox	MANUAL
Mileage	80,214 Miles Warranted	Service documents	Printout	Gears	5
Fuel Type	PETROL	Number of stamps	7	Doors	5
Colour	ORANGE/BLACK	Last service date	17/04/2026		
VIN	VF12RD11A57246221	Last service miles	79,290		

£100 ADDITIONAL FEE
 last service 17/4/26 @ 79,290 miles (7 main dealer)

Tyres

NSF
NSR
OSF
OSR
Spare