

VEHICLE INSPECTION REPORT

GV65RBZ

Nissan Juke 1.6 Tekna 5dr Xtronic

| Inspection | | Vehicle | | | nama |
|-----------------|---------------------------|--------------------|--------------|-------------|-----------|
| Serious Damage? | No | VAT | Margin | | Grape 3 |
| | | V5 | Present | | |
| Details | | | | | |
| Reg. date | 02/02/2016 | Keys | 2 | CAP Clean | £3,800.00 |
| Year | 2016 | Service history | Yes | CAP Average | £3,225.00 |
| Mileage | 94,354 Miles Warranted | Service documents | Service Book | CAP Below | £2,650.00 |
| | | Number of stamps | 6 | Gearbox | CVT |
| Fuel Type | Petrol | Last service date | 09/11/2021 | Gears | 5 |
| Colour | YELLOW | Last service miles | 68,312 | Doors | 5 |
| VIN | SJNFBAF15U7204059 | MOT Due | 29/11/2025 | | |
| Body Style | Hatchback | | | | |

£65 ADDITIONAL FEE Last service 09/11/2021 @ 68312 miles (6 MAIN DEALER SERVICES) Gearbox Fault

| NSF | HANKOOK | 5.0mm | |
|-------|---------|-------|---|
| NSR | NEXEN | 5.0mm | |
| OSF | HANKOOK | 5.0mm | |
| OSR | NEXEN | 5.0mm | _ |
| Spare | | | |

Features

- Bluetooth connection
- Park assist camera
- · Body coloured bumpers
- Front armrestSolid Paint
- Traction control
- Leather seat trim
- Cruise control
- Rear wiper Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

- Heated front seat
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation systemRadio/CD
- Climate control
- Rear headrests
- Passenger airbagRemote central locking

Photos






















Condition Check



Damage Photos



1: Wheel osf Corroded Light



2: Wheel osi Corroded Light



3: Wheel nsr Corroded Light




4: Wheel nsf Corroded Light



5: Bumper Front Poor Previous Repair Paint Flake



6: Bonnet Chipped Multiple Chips



7: Screen Front Chipped UpTo 10mm

Interior

Carpet Condition Upholstery Condition Average **Seat Condition** Odour Average

Average No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
|--------------------------|----|--|----|
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | | Gearbox Static Gear Selection (engine running) | |
| | | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| Sat nav | OK | Steering | OK |