



# VEHICLE INSPECTION REPORT

**HN18JFO**

## Fiat 500 1.2 Lounge 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	31/03/2018	Body Style	Hatchback	Last service miles	29,661
Year	2018	Keys	2	MOT Due	30/03/2027
Mileage	34,494 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	WHITE	Number of stamps	6	Doors	3
VIN	ZFA3120000J922942	Last service date	24/03/2025		

### £90 ADDITIONAL FEE

Last service 24/03/2025 at 29,661 miles- 6 services (4 main dealer)  
 Timing belt replaced 13/03/2024 at 25,411 miles

### Tyres

NSF	ROTALLA	5.0mm
NSR	ROTALLA	5.0mm
OSF	ROTALLA	5.0mm
OSR	ROTALLA	5.0mm
Spare		

## Features


- Bluetooth connection
- Radio/CD
- Air conditioning
- ABS
- Tyre pressure monitor
- Leather seat trim
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Remote central locking
- Telephone
- Fixed panoramic glass roof
- Solid Paint
- Traction control
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Door Mirror Assy of  
Scratched (Painted)  
UpTo 25mm Thru Paint



2: Door of  
Chipped  
1 To 5



3: Door osf  
Chipped  
Edge Chip



4: Bumper Front  
Chipped  
Multiple Chips



5: Bonnet  
Chipped  
1 To 5

### Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK