



VEHICLE INSPECTION REPORT

RV13CSF

Mercedes-Benz Citan 109CDI Van

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

nama
GRADE
4

Details

Reg. date	04/03/2013	VIN	WDF4156032U118650	Number of stamps	1
Year	2013	Body Style	Panel Van	Last service date	21/03/2024
Mileage	111,817 Miles Warranted	Keys	2	Last service miles	101,468
Fuel Type	DIESEL	Service history	Yes	Gearbox	MANUAL
Colour	BEIGE	Service documents	Printout	Gears	5

£100 ADDITIONAL FEE

Part V5, has green slip
 Last service 21/03/2024 at 101,468 miles- 1 service
 MOT EXPIRED
 Service spanner displayed
 Steering knocking
 Radio coded

Tyres

NSF	HANKOOK	5.0mm
NSR	HANKOOK	1.0mm
OSF	HANKOOK	5.0mm
OSR	HANKOOK	3.0mm
Spare		

Features


- Bluetooth connection
- Central locking
- Cruise control
- Cloth seat trim
- Radio/CD
- Drivers airbag

Photos





Condition Check



Damage Photos



1: Switches And Controls
Broken
Replace



2: Bonnet
Chipped
Multiple Chips



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Screen Front
Chipped
Over 10mm



5: Sill ns
Scratched
Over 25mm Thru Paint



6: Door nsf
Dented
Between 10mm + 30mm



7: Door nsr
Dented
Between 10mm + 30mm



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Fuel Flap
Missing
Replace



10: Qtr Panel nsr
Dented
Between 10mm + 30mm



11: Tailgate
Dented
With Paint Damage



12: Roof
Dented
With Paint Damage



13: Lamp osr
Broken
Replace



14: Qtr Panel osr
Dented
With Paint Damage



15: Door osr
Dented
Between 10mm + 30mm



16: Sill os
Scratched
Over 25mm Thru Paint



17: Door osf
Dented
Over 30mm



18: Wing osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	Fault
		Steering	OK