



# VEHICLE INSPECTION REPORT

**WK66WSF**

## Kia Sportage 1.7 CRDi ISG 3 5dr

| Inspection      |    | Vehicle |          |
|-----------------|----|---------|----------|
| Serious Damage? | No | VAT     | Plus VAT |
|                 |    | V5      | Present  |

nama  
GRADE  
**3**

### Details

|           |                            |                   |              |                    |            |
|-----------|----------------------------|-------------------|--------------|--------------------|------------|
| Reg. date | 15/11/2016                 | Body Style        | Estate       | Last service miles | 65,263     |
| Year      | 2016                       | Keys              | 2            | MOT Due            | 08/09/2026 |
| Mileage   | 186,064 Miles<br>Warranted | Service history   | Yes          | Gearbox            | MANUAL     |
| Fuel Type | DIESEL                     | Service documents | Service Book | Gears              | 6          |
| Colour    | BLACK                      | Number of stamps  | 6            | Doors              | 5          |
| VIN       | U5YPH815LGL190316          | Last service date | 06/04/2021   |                    |            |

### £100 ADDITIONAL FEE

Last service 06/04/2021 at 65,263 miles- 6 services (4 main dealer) Service overdue  
Struggling to get in gears

### Tyres

|     |        |       |
|-----|--------|-------|
| NSF | BUDGET | 3.0mm |
| NSR | BUDGET | 3.0mm |
| OSF | BUDGET | 3.0mm |
| OSR | BUDGET | 3.0mm |

### Spare

## Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- PAS
- Digital radio
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Navigation system
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Corroded  
Light



2: Wing osf  
Chipped  
1 To 5



3: Door osf  
Chipped  
1 To 5



4: Door osf  
Chipped  
Edge Chip



5: Door osr  
Chipped  
1 To 5



6: Wheel osr  
Corroded  
Light



7: Door osr  
Chipped  
Edge Chip



8: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



9: Bumper Rear  
Chipped  
1 To 5



10: Qtr Panel nsr  
Dented  
2 Or Less UpTo 10mm



11: Wheel nsr  
Corroded  
Light



12: Door nsr  
Dented  
2 Or Less UpTo 10mm



13: Door nsf  
Scratched  
UpTo 25mm Thru Paint



14: Wheel nsf  
Corroded  
Light



15: Wing nsf  
Chipped  
1 To 5



16: Bumper Front  
Chipped  
Multiple Chips



17: Bonnet  
Chipped  
Multiple Chips



18: Screen Front  
Chipped  
UpTo 10mm



19: Roof  
Chipped  
1 To 5



20: Door osf  
Dented  
Between 10mm + 30mm



21: Tailgate  
Dented  
Over 30mm



22: Bumper Rear Moulding  
Scuffed (Unpainted)  
Over 100mm

### Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

|                          |    |  |       |
|--------------------------|----|--|-------|
| Engine Runs              | OK | Gearbox 1st and Reverse Test                   | OK    |
| Brakes                   | OK | Clutch Slip Test from Static                   | OK    |
| Parking Brake            | OK | Gearbox Static Gear Selection (engine running) | Fault |
|                          |    | No Excessive Smoking                           | OK    |
| EML light illuminated    | OK | Oil warning light illuminated                  | OK    |
| Airbag light illuminated | OK | Service indicator light illuminated            | Fault |
| ABS light illuminated    | OK |  |       |
| Windows                  | OK | Radio  | OK    |
| Sat nav                  | OK | Steering                                       | OK    |