

VEHICLE INSPECTION REPORT

GK65VHU

Ford Kuga 2.0 TDCi 150 Zetec 5dr 2WD

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
2

Details

Reg. date	26/09/2015	Body Style	Hatchback	Last service miles	35,631
Year	2015	Keys	2	MOT Due	25/09/2026
Mileage	41,469 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Service Book	Gears	6
Colour	RED	Number of stamps	9	Doors	5
VIN	WF0AXXWPMFT35702	Last service date	28/08/2024		

Last service 28/08/2024 at 35,631 miles- 9 services

Tyres

NSF	RAPID	3.0mm
NSR	MICHELIN	3.0mm
OSF	RAPID	2.0mm
OSR	MICHELIN	3.0mm
Spare		


Features

- Bluetooth connection
- Radio/CD
- Front armrest
- Solid Paint
- Traction control
- Cloth seat trim
- Cruise control
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking

Photos



Condition Check



Damage Photos



1: Wing of
Chipped
1 To 5



2: Tailgate
Scratched
Over 25mm Thru Paint



3: Wing nsf
Chipped
1 To 5



4: Bumper Front
Chipped
Multiple Chips



5: Bonnet
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
		Steering	OK