



VEHICLE INSPECTION REPORT

GJ16ZYZ

Vauxhall Zafira 2.0 CDTi [170] SRi 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	30/03/2016	Keys	1	CAP Clean	£2,850.00
Year	2016	Service history	Yes	CAP Average	£2,350.00
Mileage	94,797 Miles Warranted	Service documents	Service Book	CAP Below	£1,850.00
Fuel Type	Diesel	Number of stamps	9	Gearbox	MANUAL
Colour	GREEN	Last service date	02/12/2024	Gears	6
VIN	W0LPD9E74G1041330	Last service miles	83,900		
Body Style	MPV	MOT Due	01/04/2026		

Last service 02/12/2024 @ 83900 miles (9 SERVICES 2 MAIN DEALER) Engine slightly noisy

Tyres

NSF	FARROAD	3.0mm
NSR	FARROAD	5.0mm
OSF	FARROAD	3.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Radio/CD
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos






Condition Check




Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Chipped
1 To 5



3: Door osr
Chipped
1 To 5



4: Wheel osr
Scratched
Over 50mm




5: Qtr Panel osr
Scratched
Over 25mm Thru Paint



6: Bumper Rear
Scratched
25 to 100mm Thru Paint



7: Wheel nsr
Scratched
Over 50mm



8: Door nsr
Scratched
UpTo 25mm Thru Paint



9: Door nsf
Scratched
Over 25mm Not Thru Paint



10: Wing nsf
Scratched
Over 25mm Not Thru Paint



11: Wheel nsf
Scratched
Over 50mm



12: Badgedecal Front
Missing
Replace



13: Sill ns
Dented
With Paint Damage

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK