



VEHICLE INSPECTION REPORT

KT69HYP

Audi Q2 SQ2 Quattro Black Edition 5dr S Tronic

nama
GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	20/01/2020	Body Style	Estate	Last service miles	50,231
Year	2020	Keys	2	MOT Due	19/01/2027
Mileage	82,723 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Petrol	Service documents	Electronic / Online	Gears	7
Colour	GREY	Number of stamps	4		
VIN	WAUZZZGAXLA021479	Last service date	08/11/2023		

£100 ADDITIONAL FEE

LAST SERVICE 08/11/2023 @ 50,231 MILES (4 SERVICES) Service due message displayed

Tyres

NSF	BRIDGESTONE	5.0mm
NSR	BRIDGESTONE	5.0mm
OSF	BRIDGESTONE	5.0mm
OSR	BRIDGESTONE	5.0mm

Spare

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Partial leather seat trim
- Cruise control
- PAS
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Solid Paint
- Isofix child seat anchor points
- Central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Poor Paint



2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wheel nsf
Scratched
Up To 50mm



4: Door nsf
Dented
Between 10mm + 30mm



5: Door nsf
Chipped
1 To 5



6: Wheel nsr
Scratched
Up To 50mm



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Wheel osr
Scratched
Over 50mm



9: Door osr
Dented
2 Or Less UpTo 10mm



10: Door osr
Chipped
1 To 5



11: Wheel osf
Scratched
Over 50mm



12: Screen Front
Chipped
UpTo 10mm



13: Wing nsf
Poor Previous Repair
Poor Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK