



VEHICLE INSPECTION REPORT

PF66MHE

PEUGEOT 108 1.2 PureTech Allure 5dr

Inspection	Vehicle
VAT	Margin
V5	TBC

Details

Reg. date	29/11/2016	Colour	BLACK	Gearbox	MANUAL
Year	2016	VIN	VF3PAHMTTCGR289661	Gears	5
Mileage	73,202 Miles Warranted	Body Style	Hatchback	Doors	5
Fuel Type	PETROL	MOT Due	12/12/2026		

Tyres

NSF
NSR
OSF
OSR
Spare

Photos



Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		

Windows

OK

Radio

OK

Steering

OK