



VEHICLE INSPECTION REPORT

WG69NVW

Fiat 500x 1.0 S Design 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	02/09/2019	Body Style	Hatchback	Last service miles	33,447
Year	2019	Keys	2	MOT Due	09/10/2026
Mileage	41,099 Miles Not Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	4	Doors	5
VIN	ZFA334000P822534	Last service date	03/07/2025		

£100 ADDITIONAL FEE

SOME SERVICES & MOTs ARE IN KMs AND MILES

LAST SERVICE 03/07/2025 @ 33,447 MILES (4 SERVICES, 2 MAIN DEALER) Service spanner displayed

Tyres

NSF	SUNNY	5.0mm
NSR	SUNNY	5.0mm
OSF	CONTINENTAL	5.0mm
OSR	SUNNY	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Partial leather seat trim
- Cruise control
- Service indicator
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Central locking
- Rear parking sensor
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



4: Wing osf
Chipped
1 To 5



5: Wheel nsf
Scratched
Over 50mm



6: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



7: Door nsf
Dented
Over 30mm



8: Door nsr
Dented
Over 30mm



9: Bumper Rear
Scratched
25 to 100mm Thru Paint




10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Qtr Panel Arch Extension os
Scuffed (Unpainted)
UpTo 100mm



12: Wheel osr
Scratched
Over 50mm



13: Door osr
Scratched
Over 25mm Thru Paint



14: Door osf
Chipped
Edge Chip



15: Wheel osf
Scratched
Over 50mm



16: Fascia Trim
Missing
Replace



17: Bumper Rear Moulding
Scratched (Painted)
Over 25mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK