



VEHICLE INSPECTION REPORT

YF69LDV

BMW X1 sDrive 20i M Sport 5dr Step Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	21/11/2019	Keys	2	CAP Clean	£15,650.00
Year	2019	Service history	Yes	CAP Average	£14,300.00
Mileage	59,920 Miles Warranted	Service documents	Electronic / Online	CAP Below	£12,950.00
Fuel Type	Petrol	Number of stamps	6	Gearbox	AUTOMATIC
Colour	GREY	Last service date	05/12/2025	Gears	7
VIN	WBA72AA0905P53913	Last service miles	53,932		
Body Style	Estate	MOT Due	20/11/2025		

£65 ADDITIONAL FEE SERVICES STORED IN ON-BOARD SYSTEM Last service 05/12/2024 @ 53932 miles
(6 MAIN DEALER SERVICES)

Tyres

NSF	CONTINENTAL	4.0mm
NSR	CONTINENTAL	5.0mm
OSF	CONTINENTAL	3.0mm
OSR	CONTINENTAL	4.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Door osf
Chipped
Edge Chip




2: Door osf
Dented
2 Or Less UpTo 10mm



3: Bumper Rear
Chipped
1 To 5



4: Bonnet
Chipped
1 To 5



5: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK