



VEHICLE INSPECTION REPORT

EX66YVD

Seat MII 1.0 75 FR Line 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	29/10/2016	Keys	2	CAP Clean	£3,100.00
Year	2016	Service history	Yes	CAP Average	£2,575.00
Mileage	82,981 Miles Warranted	Service documents	Service Book	CAP Below	£2,050.00
Fuel Type	PETROL	Number of stamps	10	Gearbox	MANUAL
Colour	WHITE	Last service date	09/09/2025	Gears	5
VIN	VSSZZZAAZHD301599	Last service miles	75,516	Doors	5
Body Style	Hatchback	MOT Due	27/09/2026		

£90 ADDITIONAL FEE

Last service 09/09/2025 at 75,516 miles- 10 services (3 main dealer) Noisy clutch / fly wheel

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Media storage
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- PAS
- Body coloured bumpers
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Rear parking sensor
- Electric door mirrors
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Rear wiper
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Sill ns
Dented
With Paint Damage



6: Door nsf
Scratched
UpTo 25mm Thru Paint



7: Door nsf
Dented
Between 10mm + 30mm



8: Door nsr
Chipped
1 To 5



9: Wheel nsr
Scratched
Up To 50mm



10: Bumper Rear
Chipped
1 To 5



11: Qtr Panel osr
Rusted
Over 5mm



12: Wheel osr
Scratched
Over 50mm



13: Door osr
Chipped
1 To 5



14: Door osf
Chipped
1 To 5



15: Wheel osf
Scratched
Over 50mm



16: Tyre osf
Damaged
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK