

VEHICLE INSPECTION REPORT

GX21ZKO

Kia Sportage 1.6 CRDi 48V ISG GT-Line 5dr DCT Auto [AWD]

inspection		venicie			nama
Serious Damage?	No	VAT	Margin		Grape.
		V5	Present		
Details					
Reg. date	01/03/2021	Keys	2	CAP Clean	£14,700.00
Year	2021	Service history	Yes	CAP Average	£13,450.00
Mileage	44,404 Miles Warranted	Service documents	Service Book	CAP Below	£12,150.00
Fuel Type	Hybrid Electric	Number of stamps	4	Gearbox	SEMI AUTO
Colour	GREY	Last service date	17/04/2025	Gears	7
VIN	U5YPK812WML994886	Last service miles	43,855		
Body Style	Estate	MOT Due	08/05/2026		

Last Service - 17.04.2025 at 43855 miles (4 services)

_		
	vre	, e
	y i c	

NSF	RAPID	5.0mm	
NSR	BUDGET	5.0mm	
OSF	RAPID	5.0mm	
OSR	DUNLOP	6.0mm	
Spare			

Features

- Bluetooth connection
- Navigation system
- Telephone
- Towbar
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- · Leather seat trim

Photos












Condition Check




Damage Photos



1: Wheel osf Scratched Up To 50mm



2: Door osf Scratched Over 25mm Thru Paint



3: Door osr Chipped 1 To 5



4: Wheel nsr Scratched Over 50mm



5: Door nsr Chipped 1 To 5



6: Wheel nsf Scratched Up To 50mm



7: Bumper Front Cracked UpTo 25mm

Interior

Carpet Condition Seat Condition

Average Average **Upholstery Condition Odour**

Average No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs OK		Gearbox 1st and Reverse Test	
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK