



VEHICLE INSPECTION REPORT

HN69YKM

Audi Q3 35 TDI Quattro Sport 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	23/09/2019	Body Style	Estate	Last service miles	22,719
Year	2019	Keys	2	MOT Due	12/08/2026
Mileage	43,001 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Printout	Gears	6
Colour	BLUE	Number of stamps	3	Doors	5
VIN	WAUZZZF31K1035949	Last service date	26/07/2023		

£90 ADDITIONAL FEE

LAST SERVICE 26/07/2023 @ 22,719 MILES (3 SERVICES, ALL MAIN DEALER)

Tyres

NSF	BRIDGESTONE	5.0mm
NSR	BRIDGESTONE	5.0mm
OSF	BRIDGESTONE	5.0mm
OSR		
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5



2: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



3: Qtr Panel osr
Chipped
1 To 5



4: Bumper Rear
Scratched
Over 100mm Thru Paint



5: Door nsr
Chipped
1 To 5



6: Bumper Front
Scratched
25 to 100mm Thru Paint



7: Bumper Front
Chipped
Multiple Chips



8: Bonnet
Chipped
1 To 5



9: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK