



VEHICLE INSPECTION REPORT

AV66KZS

Ford C-Max 1.5 TDCi Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	12/10/2016	Body Style	MPV	Last service miles	40,338
Year	2016	Keys	2	MOT Due	15/02/2027
Mileage	84,027 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	2	Doors	5
VIN	WF0VXXGCEVGL73156	Last service date	03/05/2023		

£90 ADDITIONAL FEE

Last service 03/05/2023 at 40,338 miles- 2 services

Tyres


NSF	BUDGET	5.0mm
NSR	AUTOGREEN	2.0mm
OSF	BUDGET	5.0mm
OSR	AUTOGREEN	2.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Front armrest
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Remote central locking
- Telephone
- Air conditioning
- Solid Paint
- Traction control
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Door osf
Chipped
Edge Chip



2: Door osr
Dented
With Paint Damage



3: Qtr Panel osr
Dented
With Paint Damage



4: Bumper Rear
Scratched
25 to 100mm Thru Paint



5: Door nsf
Chipped
1 To 5



6: Bumper Front
Chipped
1 To 5



7: Bonnet
Dented
With Paint Damage

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
		Steering	OK