



VEHICLE INSPECTION REPORT

GY70BXN

Peugeot 508 2.0 BlueHDi GT Line 5dr EAT8

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
2

Details

Reg. date	21/09/2020	Colour	RED	MOT Due	15/10/2026
Year	2020	VIN	VR3FHEHYRLY026499	Gearbox	AUTOMATIC
Mileage	11,380 Miles Warranted	Body Style	Hatchback	Gears	8
Fuel Type	DIESEL	Keys	2	Doors	5

Radar fault displays on dash
Bonnet and bumper out of line

Tyres


NSF	MICHELIN	5.0mm
NSR	LAUFENN	5.0mm
OSF	MICHELIN	4.0mm
OSR	MICHELIN	4.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Cruise control
- Rear parking sensor
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Heated front seat
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Chipped
Edge Chip



3: Bumper Rear
Chipped
1 To 5




4: Bumper Rear
Scratched
Up To 25mm Thru Paint



5: Door nsr
Scratched
Up To 25mm Thru Paint




6: Door nsf
Chipped
Edge Chip



7: Door nsf
Chipped
1 To 5



8: Wheel nsf
Scratched
Over 50mm



9: Bumper Front
Scratched
UpTo 25mm Thru Paint

10: Bumper Front
Chipped
Multiple Chips



11: Bonnet
Chipped
1 To 5

Interior

Carpet Condition OK
Seat Condition OK

Upholstery Condition OK
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK