



VEHICLE INSPECTION REPORT

ND18CZT

BMW 4 Series 420i M Sport 2dr Auto [Professional Media]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/05/2018	Body Style	Convertible	Last service miles	40,272
Year	2018	Keys	2	MOT Due	30/05/2027
Mileage	84,283 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	PETROL	Service documents	Printout	Gears	8
Colour	BLUE	Number of stamps	3	Doors	2
VIN	WBA4V12070EA64593	Last service date	15/05/2023		

last service 15/5/23 @ 40,272 miles (3 service) Smoke when first start cold

Tyres



NSF	BUDGET	Damaged
NSR	BUDGET	Damaged
OSF	BUDGET	5.0mm
OSR	BUDGET	6.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- PAS
- Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Radio/CD
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Heated front seat
- Service indicator
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Corroded
Light



4: Wing nsf
Chipped
1 To 5



5: Door nsf
Dented
Between 10mm + 30mm




6: Door nsf
Chipped
1 To 5



7: Wheel nsr
Scratched
Over 50mm




8: Qtr Panel nsr
Poor Previous Repair
Rippled UpTo 30%



9: Bumper Rear
Scratched
Up To 25mm Thru Paint



10: Wheel osr
Scratched
Over 50mm



11: Qtr Panel osr
Poor Previous Repair
Paint Flake



12: Door osf
Scratched
Over 25mm Thru Paint



13: Wing osf
Chipped
1 To 5



14: Wheel osf
Scratched
Over 50mm



15: Screen Front
Chipped
Over 10mm



16: Tyre nsf
Damaged
Replace



17: Tyre nsr
Damaged
Replace



18: Boot Lid
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	Fault

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		