



VEHICLE INSPECTION REPORT

MJ14PXU

Ford Focus 1.0 125 EcoBoost Zetec S 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/04/2014	VIN	WF0KXXGCBKET47253	Gearbox	MANUAL
Year	2014	Body Style	Hatchback	Gears	6
Mileage	81,931 Miles Warranted	Keys	2	Doors	5
Fuel Type	PETROL	Service history	None		
Colour	WHITE	MOT Due	22/01/2027		

£100 ADDITIONAL FEE

NO SERVICE HISTORY Engine knocks on start up

Lumpy on idle

Eml light is on

Car been plugged in and detected

Crankshaft position correlation

Tyres

NSF	BUDGET	Damaged
NSR	BUDGET	5.0mm
OSF	BUDGET	6.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Front parking sensor
- Radio/CD
- Front armrest
- Solid Paint
- Traction control
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Central locking
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wheel osr
Scratched
Up To 50mm



3: Qtr Panel osr
Rusted
UpTo 5mm



4: Wheel nsr
Scratched
Over 50mm



5: Door nsf
Chipped
1 To 5



6: Wheel nsf
Scratched
Over 50mm



7: Bumper Front
Chipped
Multiple Chips



8: Bonnet
Chipped
1 To 5



9: Roof
Chipped
1 To 5

10: Tyre nsf
Damaged
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK