



VEHICLE INSPECTION REPORT

GV66YPK

Suzuki Baleno 1.0 Boosterjet SZ5 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Buyer To Apply



Details

Reg. date	31/01/2017	Body Style	Hatchback	Last service miles	19,525
Year	2017	Keys	2	MOT Due	31/01/2027
Mileage	52,800 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	BLUE	Number of stamps	3	Doors	5
VIN	MA3EWB42S00259677	Last service date	22/01/2020		

£100 ADDITIONAL FEE

NO V5

Last service 22/01/2020 at 19,525 miles- 3 main dealer services

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Park assist camera
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check




Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Poor Previous Repair
Poor Paint



3: Door osr
Scratched
Over 25mm Thru Paint



4: Wheel osr
Scratched
Over 50mm



5: Qtr Panel osr
Dented
With Paint Damage



6: Bumper Rear
Scratched
Over 100mm Thru Paint



7: Qtr Panel nsr
Dented
With Paint Damage



8: Wheel nsr
Scratched
Over 50mm



9: Door nsr
Dented
With Paint Damage



10: Door nsf
Dented
With Paint Damage



11: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



12: Wheel nsf
Scratched
Over 50mm



13: Wing nsf
Scratched
UpTo 25mm Thru Paint



14: Headlamp ns
Broken
Replace



15: Bumper Front
Scratched
25 to 100mm Thru Paint



16: Bonnet
Chipped
1 To 5



17: Roof
Rusted
Over 5mm



18: Seat Base Cover osf
Holed
Over 3mm



19: Carpets Front
Holed
Over 3mm



20: Seat Back Cover nsr
Holed
UpTo 3mm

Interior

Carpet Condition Poor
Seat Condition Poor

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK