



VEHICLE INSPECTION REPORT

SA14FAM

Volkswagen UP 1.0 Groove Up 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	15/03/2014	Keys	1	CAP Clean	£1,600.00
Year	2014	Service history	Yes	CAP Average	£1,200.00
Mileage	140,901 Miles Warranted	Service documents	Service Book	CAP Below	£775.00
Fuel Type	PETROL	Number of stamps	7	Gearbox	MANUAL
Colour	WHITE	Last service date	25/09/2019	Gears	5
VIN	WVWZZZAAZED091695	Last service miles	66,100	Doors	3
Body Style	Hatchback	MOT Due	28/11/2026		

£100 ADDITIONAL FEE

Last service 25/09/2019 at 66,100 miles- 7 main dealer services

Tyres

NSF	COMFORSER	5.0mm
NSR	BUDGET	5.0mm
OSF	COMFORSER	5.0mm
OSR	COMFORSER	5.0mm
Spare		

Features


- Heated front seat
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear wiper
- Air conditioning
- Solid Paint
- Traction control
- Cloth seat trim
- Radio/CD
- Climate control
- ABS
- Tyre pressure monitor
- Alloy wheels
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Over 5mm



2: Wheel of
Corroded
Light



3: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



4: Door osf
Dented
With Paint Damage



5: Qtr Panel osr
Rusted
Over 5mm



6: Wheel osr
Corroded
Light



7: Bumper Rear
Poor Previous Repair
Paint Flake



8: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm



9: Wheel nsf
Corroded
Light



10: Door nsf
Chipped
Edge Chip



11: Door nsf
Scratched
UpTo 25mm Thru Paint



12: Wheel nsf
Corroded
Light



13: Wing nsf
Chipped
1 To 5



14: Bumper Front
Scratched
UpTo 25mm Thru Paint



15: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK