



VEHICLE INSPECTION REPORT

SB59VZT

VOLKSWAGEN POLO 1.4 SE 5dr DSG

Inspection

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	31/12/2009	Body Style	Hatchback	MOT Due	06/11/2026
Year	2009	Service history	Yes	Gearbox	SEMI AUTO
Mileage	49,000 Miles Warranted	Service documents	Service Book	Gears	7
Fuel Type	PETROL	Number of stamps	6	Doors	5
Colour	GREY	Last service date	28/03/2025		
VIN	WVWZZZ6RZAU008672	Last service miles	44,739		

last service 28/3/25 @ 44,739 miles (6 services 2 main dealer) book & print

Tyres

NSF
NSR
OSF
OSR
Spare