



VEHICLE INSPECTION REPORT

AK21TRV

Land Rover Discovery Sport 1.5 P300e R-Dynamic HSE 5dr Auto [5 Seat]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/03/2021	Body Style	Estate	Last service miles	57,373
Year	2021	Keys	2	MOT Due	12/04/2027
Mileage	66,395 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	HYBRID ELECTRIC	Service documents	Printout	Gears	8
Colour	RED	Number of stamps	5	Doors	5
VIN	SALCA2ATXLH881447	Last service date	04/06/2025		

£100 ADDITIONAL FEE

last service 4/6/25 @ 57,373 miles (5 services 4 main dealer)

Tyres

NSF	HANKOOK	3.0mm
NSR	HANKOOK	3.0mm
OSF	HANKOOK	3.0mm
OSR	HANKOOK	4.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Telephone
- Fixed panoramic glass roof
- Electrically adjustable passenger seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Front armrest
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Front electric windows
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Rear electric windows
- Metallic Paint
- Traction control
- Leather seat trim
- ABS
- Tyre pressure monitor
- Alloy wheels
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Chipped
Edge Chip



3: Door osr
Chipped
1 To 5



4: Door osr
Chipped
Edge Chip




5: Bumper Rear
Scratched
Up To 25mm Thru Paint



6: Door nsr
Chipped
1 To 5




7: Door nsf
Chipped
1 To 5



8: Bumper Front
Scratched
25 to 100mm Thru Paint



9: Bumper Front
Chipped
Multiple Chips



10: Bonnet
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		