



VEHICLE INSPECTION REPORT

GK19HXS

Kia Sportage 1.6 CRDi ISG 2 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	01/03/2019	Body Style	Estate	Last service miles	60,377
Year	2019	Keys	2	MOT Due	08/02/2027
Mileage	68,504 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	6	Doors	5
VIN	U5YPH812LKL670233	Last service date	25/02/2025		

£100 ADDITIONAL FEE

Last Service - 25.02.2025 at 60377 miles (6 services) EML light on car has been plugged in and detects code p226d

Tyres

NSF	LAUFENN	3.0mm
NSR	LAUFENN	6.0mm
OSF	LAUFENN	3.0mm
OSR	LAUFENN	6.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Door osf
Chipped
Edge Chip



3: Wheel osr
Corroded
Light



4: Door osr
Chipped
1 To 5



5: Bumper Rear
Chipped
1 To 5



6: Wheel nsr
Scratched
Over 50mm



7: Door nsr
Dented
Over 30mm



8: Door nsf
Chipped
Edge Chip



9: Wheel nsf
Scratched
Over 50mm



10: Bumper Front
Scratched
25 to 100mm Thru Paint



11: Bonnet
Chipped
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK