



VEHICLE INSPECTION REPORT

FL71KZE

Skoda Superb 1.4 TSI iV SE Technology DSG 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	04/09/2021	Body Style	Estate	Last service miles	89,955
Year	2021	Keys	2	MOT Due	03/09/2026
Mileage	95,034 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	HYBRID ELECTRIC	Service documents	Printout	Gears	6
Colour	SILVER	Number of stamps	5	Doors	5
VIN	TMBKW7NP1M7077558	Last service date	20/03/2026		

£100 ADDITIONAL FEE

Last service 20/03/2026 at 89,955 miles- 5 main dealer services Type 2 and 3 pin charging cable in boot

Tyres

NSF	MICHELIN	3.0mm
NSR	BRIDGESTONE	5.0mm
OSF	MICHELIN	3.0mm
OSR	MICHELIN	4.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Radio/CD
- Climate control
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Heated front seat
- Telephone
- Air conditioning
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5




2: Door osr
Chipped
1 To 5



3: Qtr Panel osr
Dented
Between 10mm + 30mm



4: Qtr Panel osr
Chipped
1 To 5



5: Bumper Rear
Chipped
Multiple Chips



6: Door nsr
Chipped
Edge Chip



7: Door nsr
Chipped
1 To 5




8: Wheel nsf
Scratched
Up To 50mm



9: Bumper Front
Chipped
Multiple Chips



10: Bonnet
Chipped
Multiple Chips



11: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK