



VEHICLE INSPECTION REPORT

LV65LNO

Vauxhall Mokka 1.6 CDTi Tech Line 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/09/2015	Body Style	Hatchback	Last service miles	151,231
Year	2015	Keys	2	MOT Due	28/09/2026
Mileage	154,646 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	11	Doors	5
VIN	W0LJC7EC2FB261648	Last service date	17/03/2026		

£100 ADDITIONAL FEE

Last service 17/03/2026 at 151,231 miles- 11 services (7 main dealer) Noisy engine when revved
And intermittent noise when idle

Tyres

NSF	BRIDGESTONE	5.0mm
NSR	HIFLY	5.0mm
OSF	BRIDGESTONE	5.0mm
OSR	HIFLY	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Solid Paint
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Chipped
Edge Chip



4: Other
N/A
N/A



5: Door osr
Dented
Over 30mm



6: Qtr Panel osr
Dented
Over 30mm



7: Tailgate
Dented
With Paint Damage



8: Door nsr
Dented
2 Or Less UpTo 10mm



9: Door nsf
Dented
Between 10mm + 30mm



10: Wing nsf
Chipped
1 To 5



11: Wing nsf
Dented
2 Or Less UpTo 10mm



12: Wheel nsf
Scratched
Over 50mm



13: Bumper Front
Cracked
Over 25mm



14: Bonnet
Chipped
Multiple Chips

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK