



VEHICLE INSPECTION REPORT

GU12DNF

Toyota Yaris 1.33 VVT-i T Spirit 5dr Multidrive S

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	06/03/2012	Keys	2	CAP Clean	£4,700.00
Year	2012	Service history	Yes	CAP Average	£4,100.00
Mileage	77,735 Miles Warranted	Service documents	Service Book	CAP Below	£3,475.00
Fuel Type	Petrol	Number of stamps	10	Gearbox	CVT
Colour	SILVER	Last service date	12/03/2024	Gears	1
VIN	VNKKJ3D340A054009	Last service miles	72,465	Doors	5
Body Style	Hatchback	MOT Due	20/03/2026		

Last Service - 12.03.2024 at 72465 miles (10 main dealer services)

Tyres

NSF	DUNLOP	6.0mm
NSR	DUNLOP	5.0mm
OSF	DUNLOP	5.0mm
OSR	DUNLOP	6.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Fixed panoramic glass roof
- Rear electric windows
- Drivers airbag
- Cloth seat trim
- Navigation system
- Radio/CD
- Air conditioning
- Rear headrests
- Traction control
- Alloy wheels
- Park assist camera
- Body coloured bumpers
- Climate control
- Metallic Paint
- Central locking
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wing osf
Poor Previous Repair
Poor Paint



2: Wheel osf
Scratched
Over 50mm



3: Door osr
Scratched
Over 25mm Not Thru Paint



4: Bumper Rear
Scratched
25 to 100mm Thru Paint



5: Qtr Panel nsr
Poor Previous Repair
Poor Paint



6: Door nsr
Scratched
Over 25mm Not Thru Paint



7: Bumper Front
Poor Previous Repair
Poor Paint



8: Bonnet
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		