



VEHICLE INSPECTION REPORT

HJ20EEP

Volkswagen Golf 1.5 TSI EVO 150 Match Edition 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	10/03/2020	Body Style	Hatchback	Last service miles	45,483
Year	2020	Keys	2	MOT Due	22/01/2027
Mileage	52,781 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	PETROL	Service documents	Printout	Gears	7
Colour	SILVER	Number of stamps	3	Doors	5
VIN	WVVZZZAUZLW101638	Last service date	13/03/2025		

£100 ADDITIONAL FEE

last service 13/3/25 @ 45,483 miles (3 services 2 main dealer)

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wing nsf
Dented
Between 10mm + 30mm



4: Door nsf
Poor Previous Repair
Poor Paint



5: Sill ns
Dented
With Paint Damage



6: Door nsr
Dented
Over 30mm



7: Qtr Panel nsr
Poor Previous Repair
Rippled UpTo 30%



8: Bumper Rear
Poor Previous Repair
Poor Paint



9: B Post ns
Poor Previous Repair
Poor Paint



10: Door osr
Poor Previous Repair
Poor Paint



11: Door osf
Dented
Between 10mm + 30mm



12: Door osf
Chipped
Multiple Chips



13: Wing osf
Poor Previous Repair
Poor Paint



14: Other
N/A
N/A

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK