



VEHICLE INSPECTION REPORT

GN63CWP

Fiat 500 0.9 TwinAir Colour Therapy 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/10/2013	Body Style	Hatchback	Last service miles	82,332
Year	2013	Keys	2	MOT Due	09/06/2027
Mileage	88,225 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	RED	Number of stamps	3	Doors	3
VIN	ZFA3120000J019405	Last service date	29/05/2024		

last service 29/5/24 @ 82,332 miles (3 services 1 main dealer)
clutch replaced 29/1/25 mileage not recorded Noisy front suspension
Blowing exhaust

Tyres

NSF	BUDGET	6.0mm
NSR	BUDGET	6.0mm
OSF	BUDGET	6.0mm
OSR	FARROAD	5.0mm
Spare		

Features


- PAS
- Body coloured bumpers
- Front electric windows
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Front head restraints
- Metallic Paint
- Passenger airbag
- Partial leather seat trim
- Steering wheel mounted controls
- Front fog lights
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Side airbags
- Steel wheels
- Radio/CD
- Folding rear seats
- Steering wheel rake adjustment
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5



2: Door osf
Chipped
1 To 5



3: Door osf
Chipped
Edge Chip



4: Qtr Panel osr
Poor Previous Repair
Paint Flake



5: Bumper Rear
Scratched
Over 100mm Thru Paint



6: Rear TowEye Cvr
Missing
Replace



7: Qtr Panel nsr
Poor Previous Repair
Poor Paint



8: Door nsf
Chipped
1 To 5



9: Door nsf
Chipped
Edge Chip



10: Wing nsf
Dented
2 Or Less UpTo 10mm



11: Wing nsf
Chipped
1 To 5



12: Bumper Front
Poor Previous Repair
Paint Flake



13: Bonnet
Poor Previous Repair
Paint Flake



14: Roof
Poor Previous Repair
Paint Flake



15: Other
N/A
N/A

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK