



VEHICLE INSPECTION REPORT

BF13MHE

Audi A6 2.0 TDI SE 4dr Multitronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	10/05/2013	Body Style	Saloon	Last service miles	146,087
Year	2013	Keys	2	MOT Due	12/05/2027
Mileage	148,927 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	DIESEL	Service documents	Printout	Gears	8
Colour	BLACK	Number of stamps	11	Doors	4
VIN	WAUZZZ4G6DN105754	Last service date	09/05/2025		

last service 9/5/25 @ 146,087 miles (11 services 8 main dealer) GEARBOX MALFUNCTION

Tyres

NSF	SUNNY	5.0mm
NSR	GOODYEAR	5.0mm
OSF	SUNNY	5.0mm
OSR	TOYO	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- PAS
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Wing osf
Scratched
Over 25mm Thru Paint



3: Door osf
Chipped
1 To 5



4: Door osf
Chipped
Edge Chip



5: Door osr
Chipped
1 To 5



6: Wheel osr
Scratched
Over 50mm



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Qtr Panel nsr
Poor Previous Repair
Poor Paint



9: Wheel nsr
Scratched
Over 50mm



10: Door nsr
Chipped
Over 5mm



11: Door nsf
Chipped
Multiple Chips



12: Wheel nsf
Scratched
Over 50mm



13: Other
N/A
N/A



14: Bumper Front
Poor Previous Repair
Paint Flake



15: Bonnet
Chipped
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK