



VEHICLE INSPECTION REPORT

YG15OPP

Seat Leon 2.0 TDI 184 FR 5dr [Technology Pack]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	05/06/2015	Body Style	Hatchback	Last service miles	92,048
Year	2015	Keys	2	MOT Due	20/10/2026
Mileage	102,750 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	8	Doors	5
VIN	VSSZZZ5FZFR051950	Last service date	20/01/2025		

£90 ADDITIONAL FEE
Last service 20/01/2025 at 92,048 miles- 8 services (4 main dealer)
Clutch replaced 18/12/2025 at 98,849 miles
Cambelt replaced 29/0/2026 at 102,306 miles

Tyres		
NSF	BUDGET	6.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	6.0mm
OSR	RAPID	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Solid Paint
- Traction control
- Cloth seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Front parking sensor
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Door osr
Chipped
1 To 5



2: Door osf
Chipped
Edge Chip



3: Wheel osr
Corroded
Light



4: Bumper Rear
Chipped
Multiple Chips



5: Wheel nsr
Scratched
Over 50mm



6: Door nsf
Chipped
Edge Chip



7: Wheel nsf
Scratched
Over 50mm




8: Bonnet
Chipped
Multiple Chips



9: Bumper Front
Chipped
Multiple Chips



10: A Post os
Chipped
1 To 5



11: Screen Front
Chipped
UpTo 10mm



12: Roof
Chipped
1 To 5



13: Wing nsf
Dented
Between 10mm + 30mm



14: Door nsf
Dented
Over 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK