



VEHICLE INSPECTION REPORT

GC18DSU

Mercedes-Benz A Class A180d Sport Premium Plus 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	17/07/2018	Body Style	Hatchback	Last service miles	9,558
Year	2018	Keys	2	MOT Due	16/07/2027
Mileage	9,696 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	DIESEL	Service documents	Printout	Gears	7
Colour	SILVER	Number of stamps	4	Doors	5
VIN	WDD1770032J020627	Last service date	30/06/2026		

£90 ADDITIONAL FEE

last service 30/6/26 @ 9,558 miles (4 services 1 main dealer)

mileage recorded incorrectly on MOT history in 2021

Tyres

NSF	BRIDGESTONE	6.0mm
NSR	BRIDGESTONE	6.0mm
OSF	BRIDGESTONE	6.0mm
OSR	BRIDGESTONE	6.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Digital radio
- Air conditioning
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Cruise control
- PAS
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Electric door mirrors
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Partial leather seat trim
- Heated front seat
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Dented
Over 30mm



3: Wing nsf
Chipped
1 To 5



4: Door nsf
Dented
2 Or Less UpTo 10mm



5: Bumper Rear
Scratched
25 to 100mm Thru Paint



6: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



7: Door osr
Chipped
1 To 5



8: Door osf
Chipped
Edge Chip



9: Wing of
Chipped
1 To 5

10: Bonnet
Dented
Between 10mm + 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK