



VEHICLE INSPECTION REPORT

HX16YJS

Seat Leon 1.4 EcoTSI 150 FR 5dr [Technology Pack]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	01/03/2016	Body Style	Estate	Last service miles	119,233
Year	2016	Keys	1	MOT Due	28/02/2027
Mileage	124,850 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	11	Doors	5
VIN	VSSZZZ5FZGR102739	Last service date	04/12/2025		

£90 ADDITIONAL FEE

LAST SERVICE 04/12/2025 @ 119,233 MILES (11 SERVICES, 6 MAIN DEALER) Low clutch

Tyres

NSF	FALKEN	Damaged
NSR	FALKEN	5.0mm
OSF	FALKEN	5.0mm
OSR	FALKEN	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Solid Paint
- Traction control
- Cloth seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Front parking sensor
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Scratched
Over 25mm Thru Paint



4: Door osr
Chipped
1 To 5



5: Door osr
Chipped
Edge Chip



6: Qtr Panel osr
Chipped
1 To 5



7: Bumper Rear
Chipped
Multiple Chips



8: Wheel nsr
Scratched
Over 50mm



9: Door nsr
Chipped
Edge Chip



10: Wheel nsf
Scratched
Over 50mm




11: Wing nsf
Chipped
1 To 5



12: Bumper Front
Chipped
Multiple Chips



13: Bonnet
Chipped
1 To 5



14: Screen Front
Chipped
UpTo 10mm



15: Roof
Chipped
1 To 5



16: Bumper Rear
Scratched
25 to 100mm Thru Paint



17: Tyre nsf
Damaged
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK