



VEHICLE INSPECTION REPORT

HK62DGV

Renault Scenic 1.6 VVT Dynamique TomTom 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
5

Details

Reg. date	18/12/2012	Body Style	MPV	Last service miles	53,915
Year	2012	Keys	2	MOT Due	22/09/2026
Mileage	58,045 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	1	Doors	5
VIN	VF1JZ1U0248314363	Last service date	14/06/2025		

LAST SERVICE 14/06/2025 @ 53,915 MILES (1 SERVICE) Front bumper out of line

Tyres

NSF	SAILUN	5.0mm
NSR	AUTOGREEN	5.0mm
OSF	SAILUN	5.0mm
OSR	AUTOGREEN	5.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Front electric windows
- ABS
- Central locking
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Rear electric windows
- Drivers airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Telephone
- Air conditioning
- Metallic Paint
- Traction control
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Scratched
UpTo 25mm Thru Paint



3: Door osf
Chipped
1 To 5



4: Door osr
Dented
2 Or Less UpTo 10mm



5: Door osr
Chipped
1 To 5



6: Qtr Panel osr
Dented
Over 30mm



7: Tailgate
Dented
With Paint Damage



8: Bumper Rear
Poor Previous Repair
Paint Flake



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Wheel nsr
Scratched
Over 50mm



11: Door nsr
Scratched
Over 25mm Thru Paint



12: Door nsf
Scratched
Over 25mm Thru Paint



13: Wing nsf
Scratched
Over 25mm Thru Paint



14: Wheel nsf
Scratched
Over 50mm



15: Bumper Front
Poor Previous Repair
Poor Paint




16: Bonnet
Chipped
Multiple Chips



17: Carpets Front
Holed
Over 3mm



18: Seat Base Cover osf
Torn
Over 3mm



19: Roof
Dented
Over 30mm



20: Headrest Assy Rear Seat Centr
Missing
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK