



VEHICLE INSPECTION REPORT

GH16EWS

Ford Kuga 1.5 EcoBoost Zetec 5dr 2WD

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	22/08/2016	Body Style	Hatchback	Last service miles	14,826
Year	2016	Keys	1	MOT Due	26/08/2026
Mileage	78,603 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	6
Colour	BLUE	Number of stamps	2	Doors	5
VIN	WF0AXXWPMAGD86690	Last service date	30/08/2018		

£100 ADDITIONAL FEE

Last Service - 30.08.2018 at 14826 miles (2 services) Noisy engine

Gear selector fault

Tyres

NSF	BUDGET	3.0mm
NSR	NEXEN	5.0mm
OSF	BUDGET	3.0mm
OSR	NEXEN	3.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

Photos





Condition Check




Damage Photos



1: Wing osf
Chipped
1 To 5




2: Door osr
Chipped
1 To 5



3: Tailgate
Chipped
1 To 5



4: Bumper Rear
Chipped
1 To 5




5: Door nsf
Chipped
Edge Chip




6: Door nsf
Chipped
1 To 5



7: Bonnet
Poor Previous Repair
Paint Flake



8: Bumper Front
Chipped
Multiple Chips



9: Roof
Chipped
1 To 5



10: Screen Front
Chipped
UpTo 10mm



11: Door osf
Dented
Over 30mm



12: Door nsr
Dented
With Paint Damage



13: Tailgate
Dented
Between 10mm + 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK