



VEHICLE INSPECTION REPORT

LC67UJW

Vauxhall Vivaro 2700 1.6CDTI 120PS Sportive H1 Van

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/11/2017	Colour	BLACK	Service history	None
Year	2017	VIN	W0VF7G603JV610779	MOT Due	17/12/2026
Mileage	140,688 Miles Warranted	Body Style	Panel Van	Gearbox	MANUAL
Fuel Type	DIESEL	Keys	2	Gears	6

£100 ADDITIONAL FEE
NO SERVICE


Tyres

NSF	EVERGREEN	5.0mm
NSR	BUDGET	5.0mm
OSF	EVERGREEN	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- Air conditioning
- Central locking
- Cruise control
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Metallic Paint
- Radio/CD
- Drivers airbag

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Carpets Front
Holed
Over 3mm



3: Bonnet
Chipped
Multiple Chips



4: Screen Front
Cracked
Replace



5: Bumper Front
Scratched
25 to 100mm Thru Paint



6: Door Mirror Assy nsf
Broken
Replace



7: Wing nsf
Scratched
Over 25mm Thru Paint



8: Door nsf
Chipped
Edge Chip



9: B Post ns
Scratched
Over 25mm Thru Paint



10: Door nsr
Dented
With Paint Damage



11: Qtr Panel nsr
Dented
With Paint Damage



12: Bumper Rear
Cracked
Over 25mm



13: Tailgate
Dented
With Paint Damage



14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Panel Front
Scratched
Over 25mm Thru Paint



16: Door osf
Scratched
Over 25mm Thru Paint



17: Other
N/A
N/A



18: Wing osf
Chipped
1 To 5



19: Roof
Dented
Over 30mm

Interior

Carpet Condition Poor
Seat Condition Poor

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK