



VEHICLE INSPECTION REPORT

OE70CWF

Land Rover Discovery Sport 1.5 P300e R-Dynamic HSE 5dr Auto [5 Seat]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	12/11/2020	Body Style	Estate	Last service miles	48,273
Year	2020	Keys	2	MOT Due	30/03/2027
Mileage	50,895 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	HYBRID ELECTRIC	Service documents	Printout	Gears	8
Colour	RED	Number of stamps	5	Doors	5
VIN	SALCA2AT8LH874285	Last service date	31/03/2026		

£90 ADDITIONAL FEE

Last service 31/03/2026 at 48,273 miles- 5 services (3 main dealer) 3 pin charging cable in boot


Tyres



NSF	PIRELLI	6.0mm
NSR	MAXXIS	5.0mm
OSF	MAXXIS	5.0mm
OSR	MAXXIS	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Telephone
- Fixed panoramic glass roof
- Electrically adjustable passenger seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Rear electric windows
- Drivers airbag
- Central locking

Photos






Condition Check




Damage Photos



1: Door osf
Chipped
Edge Chip



2: Door osf
Chipped
1 To 5



3: Door nsf
Chipped
1 To 5

4: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



5: Bumper Front
Scratched
UpTo 25mm Thru Paint

6: Bonnet
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		