



# VEHICLE INSPECTION REPORT

**FN09OXB**

## Ford Fiesta 1.25 Style 3dr [82]

| Inspection      |    | Vehicle |           |
|-----------------|----|---------|-----------|
| Serious Damage? | No | VAT     | Margin    |
|                 |    | V5      | Photocopy |



### Details

|           |                            |                   |              |                    |            |
|-----------|----------------------------|-------------------|--------------|--------------------|------------|
| Reg. date | 01/03/2009                 | Body Style        | Hatchback    | Last service miles | 69,013     |
| Year      | 2009                       | Keys              | 1            | MOT Due            | 01/12/2026 |
| Mileage   | 132,180 Miles<br>Warranted | Service history   | Yes          | Gearbox            | MANUAL     |
| Fuel Type | PETROL                     | Service documents | Service Book | Gears              | 5          |
| Colour    | RED                        | Number of stamps  | 2            | Doors              | 3          |
| VIN       | WF0GXXGAJG8T61491          | Last service date | 08/06/2017   |                    |            |

£90 ADDITIONAL FEE

LAST SERVICE 08/06/2017 @ 69,013 MILES (2 SERVICES, BOTH MAIN DEALER) Exhaust blowing

### Tyres

|       |         |       |
|-------|---------|-------|
| NSF   | BUDGET  | 5.0mm |
| NSR   | BUDGET  | 5.0mm |
| OSF   | BUDGET  | 5.0mm |
| OSR   | JOYROAD | 5.0mm |
| Spare |         |       |

## Features


- PAS
- Body coloured bumpers
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Height adjustable drivers seat
- Metallic Paint
- Passenger airbag
- Steel wheels
- Steering wheel mounted controls
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Radio/CD
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bumper Front  
Cracked  
Over 25mm



2: Bonnet  
Chipped  
Multiple Chips



3: Wheel Trim nsf  
Missing  
Replace




4: Wing nsf  
Scratched  
UpTo 25mm Thru Paint



5: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Thru Paint



6: A Post ns  
Chipped  
Over 5mm



7: Door nsf  
Dented  
With Paint Damage



8: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



9: Tailgate  
Poor Previous Repair  
Paint Flake



10: Spoiler Rear  
Scratched (Painted)  
Over 25mm Thru Paint




11: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



12: Qtr Panel osr  
Dented  
With Paint Damage



13: Door osf  
Dented  
Over 30mm



14: Wing osf  
Poor Previous Repair  
Paint Flake



15: Roof  
Dented  
Over 30mm

Interior

|                  |         |                      |         |
|------------------|---------|----------------------|---------|
| Carpet Condition | Average | Upholstery Condition | Average |
| Seat Condition   | Average | Odour                | No      |

Vehicle Inspection Report

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

|                          |    |                                                |    |
|--------------------------|----|------------------------------------------------|----|
| Engine Runs              | OK | Gearbox 1st and Reverse Test                   | OK |
| Brakes                   | OK | Clutch Slip Test from Static                   | OK |
| Parking Brake            | OK | Gearbox Static Gear Selection (engine running) | OK |
|                          |    | No Excessive Smoking                           | OK |
| EML light illuminated    | OK | Oil warning light illuminated                  | OK |
| Airbag light illuminated | OK | Service indicator light illuminated            | OK |
| ABS light illuminated    | OK |                                                |    |
| Windows                  | OK | Radio                                          | OK |
|                          |    | Steering                                       | OK |